Versa-Pac Foam Layer Return Instructions

Encoder Products Company is committed to incorporating practices that address todays environmental issues. Reusing and recycling the foam layer from EPC's Versa-Pak shipping containers is one great way to lessen our impact on the environment. If you would like to help, just follow these simple steps to return your Versa-Pak foam layers - we'll even pick up the shipping.

Step 1

Use an empty Versa-Pac to collect all foam layers normally used to ship product. This includes both solid layers and layers with cutouts. Please shield foam from UV light as it will discolor.

Step 1

Step 2

After Versa-Pac is filled with foam, tape up all sides.

Step 2

Step 3

Combine two Versa-Pacs filled with foam or for smaller amounts of foam, slide the top Versa-Pac over the bottom one.

Step 3

Step 4

Securely tape the joints where the Versa-Pacs meet to make one large shipping container.

Step 4

Step 5

Contact EPC Customer Service at 800-366-5412 and ask for a prepaid UPS return shipping label.

Technical Bulletin 531

ACCU≫CODER™
by **Encoder Products Company**

TB531, Rev. A, 09/2011 Page 1/1